



*Smoke
Clearance Tests*

Leading The Way To a Healthy Workspace






1 Extraction off - Lights on



2 Smoke machine on



3 ...2 minutes...



4 Smoke machine off - White out




HSE 261 recommends that a smoke clearance test is included in the periodic thorough maintenance examination of any spray booth. Using large professional smoke machines, FUMEX Ltd can carry out the test quickly and efficiently, then supply you with certificates for display on all booth entrances.




5 Start extraction & timer



6 Inspect seals & ducting for leakage



7 Smoke clear - Test complete



8 Certificate for display



Fumex Limited, Unit 11,
Hillfoot Industrial Estate
23 Hoyland Road,
Sheffield S3 8AB

FUMEX LTD

Tel: 0114 234 1114
Fax: 0114 234 1441
E: info@fumexltd.co.uk
W: www.fumexltd.co.uk

